






















Map Ref #	APN	Built Date (circa)	Address	Architectural Style	Primary Number	OHP Status Code	City HRI Designation Classification	Survey Notes	Evaluation Recommendation	Photograph 1	Photograph 2
3	23506030	1930	1145 N 2ND ST SAN JOSE 95112-4954	Minimal Traditional	P43-001537	6Y	N/A	Displays original windows, façade door, wall cladding, and exterior brick chimney. Evaluated as individually ineligible for listing in the National Register. Has not been previously evaluated for the California Register or San Jose Historic Resources Inventory.	Yes		
4	23506031	1927	1141 N 2ND ST SAN JOSE 95112-4954	Tudor Revival	N/A	N/A	N/A	Displays replacement windows and doors.	Yes		
5	23506032	1927	1131 N 2ND ST SAN JOSE 95112-4954	Minimal Traditional	N/A	N/A	N/A	Displays replacement stucco wall cladding, vinyl windows, and facade door, as well as a major two-story addition on the west side of the house.	Yes		
7	23506033	1928	1129 N 2ND ST SAN JOSE 95112-4954	Tudor Revival	N/A	N/A	N/A	Displays replacement windows.	Yes		





Map Ref #	APN	Built Date (circa)	Address	Architectural Style	Primary Number	OHP Status Code	City HRI Designation Classification	Survey Notes	Evaluation Recommendation	Photograph 1	Photograph 2
8	23506034	1926	1127 N 2ND ST SAN JOSE 95112-4954	Minimal Traditional	N/A	N/A	N/A	Displays original leaded glass, as well as replacement windows and doors.	Yes		
10	23506035	1928	1125 N 2ND ST SAN JOSE 95112-4954	Tudor Revival	N/A	N/A	N/A	Displays original and replacement windows and doors.	Yes		
12	23507068	1967	1120 N 1ST ST SAN JOSE 95112-4924	Contemporary	N/A	N/A	N/A	Displays original windows, doors and cladding, and original gas pump canopy.	Yes		
13	23507036	1930	1123 N 2ND ST SAN JOSE 95112-4953	Spanish Colonial Revival	N/A	N/A	N/A	Displays original windows.	Yes		





Map Ref #	APN	Built Date (circa)	Address	Architectural Style	Primary Number	OHP Status Code	City HRI Designation Classification	Survey Notes	Evaluation Recommendation	Photograph 1	Photograph 2
14	23507037	1930	1121 N 2ND ST SAN JOSE 95112-4953	Minimal Traditional	N/A	N/A	N/A	Displays replacement windows and doors.	Yes		
15	23507038	1939	1119 N 2ND ST SAN JOSE 95112-4953	Minimal Traditional	N/A	N/A	N/A	Displays replacement windows and doors. Likely large addition at back of residence.	Yes		
17	23507067	1953	1114 N 1ST ST SAN JOSE 95112-4924	Contemporary	N/A	N/A	N/A	Displays original windows, doors, and wall cladding. Stone wall cladding added to the west and south elevations.	Yes		
18	23507039	1930	1115 N 2ND ST SAN JOSE 95112-4953	Tudor Revival	N/A	N/A	N/A	Displays replacement windows.	Yes		





Map Ref #	APN	Built Date (circa)	Address	Architectural Style	Primary Number	OHP Status Code	City HRI Designation Classification	Survey Notes	Evaluation Recommendation	Photograph 1	Photograph 2
19	23507066	1930	1106 N 1ST ST SAN JOSE 95112-4924	Spanish Colonial Revival	N/A	N/A	N/A	Property contains two buildings: a circa 1960 apartment building and a circa 1930 single-family residence. According to the homeowner, the residence was relocated from the location of the apartment building to its current location at an unknown date.	Yes		
20	23507040	1940	1111 N 2ND ST SAN JOSE 95112-4953	Spanish Colonial Revival	N/A	N/A	N/A	Displays original windows.	Yes		
22	23507041	1933	1107 N 2ND ST SAN JOSE 95112-4953	Spanish Colonial Revival	N/A	N/A	N/A	Displays replacement windows, doors, and wall cladding.	Yes		
23	23507042	1936	1101 N 2ND ST SAN JOSE 95112-4953	Spanish Colonial Revival	N/A	N/A	N/A	Displays replacement windows and doors.	Yes		





Map Ref #	APN	Built Date (circa)	Address	Architectural Style	Primary Number	OHP Status Code	City HRI Designation Classification	Survey Notes	Evaluation Recommendation	Photograph 1	Photograph 2
24	23507064	1939	1052 N 1ST ST SAN JOSE 95112-4922	Streamline Moderne	N/A	N/A	N/A	Displays replacement windows, doors, and stone wall cladding from circa 1960. A rooftop "Bad Boys Bail Bonds" sign is located at the northwest corner of the building. The building was previously evaluated as ineligible for listing in the National Register, California Register, and San Jose Historic Resources Inventory due to lack of historic significance.	No		
27	23507045	1940	1055 N 2ND ST SAN JOSE 95112-4931	Minimal Traditional	N/A	N/A	N/A	Displays original windows.	Yes		
28	23507046	1930	1019 N 2ND ST SAN JOSE 95112-4931	Minimal Traditional	N/A	N/A	N/A	Displays original windows; has possible wall cladding replacement.	Yes		
29	23507047	1929	1015 N 2ND ST SAN JOSE 95112-4931	Tudor Revival	N/A	N/A	N/A	Displays original windows and wood board wall cladding.	Yes		





Map Ref #	APN	Built Date (circa)	Address	Architectural Style	Primary Number	OHP Status Code	City HRI Designation Classification	Survey Notes	Evaluation Recommendation	Photograph 1	Photograph 2
30	23507069	1968	1002 N 1ST ST SAN JOSE 95112-4922	Contemporary	N/A	N/A	N/A	Original building with replacement pumps and canopy. The building was previously evaluated as ineligible for listing in the National Register, California Register, and San Jose Historic Resources Inventory due to lack of historic significance.	No		
31	23507048	1930	1006 N 2ND ST SAN JOSE 95112-4931	Craftsman	N/A	N/A	N/A	Displays original windows and wood board wall cladding. Has a large two-story addition with unknown construction date.	Yes		
32	23507049	1931	1001 N 2ND ST SAN JOSE 95112-4931	Minimal Traditional	N/A	N/A	N/A	Displays replacement windows, doors, and vinyl wall cladding.	Yes		
33	23507053	1929	15 E YOUNGER AVE SAN JOSE 95112-4917	Folk	N/A	N/A	N/A	Displays replacement facade door and windows. The chimney has been re clad in stucco. Maintains original double beveled wood siding.	Yes		





Map Ref #	APN	Built Date (circa)	Address	Architectural Style	Primary Number	OHP Status Code	City HRI Designation Classification	Survey Notes	Evaluation Recommendation	Photograph 1	Photograph 2
34	23507052	1924	17 E YOUNGER AVE SAN JOSE 95112-4917	Craftsman	N/A	N/A	N/A	Displays replacement windows and doors, and possible cladding replacement.	Yes		
35	23507051	1929	19 E YOUNGER AVE SAN JOSE 95112-4917	Spanish Colonial Revival	N/A	N/A	N/A	Displays replacement windows, door, and wall cladding. Possible façade room addition.	Yes		
36	23507050	1924	49 E YOUNGER AVE SAN JOSE 95112-4917	Craftsman	N/A	N/A	N/A	Displays replacement windows, doors and wall cladding.	Yes		
37	23508001	1964	990 N 1ST ST SAN JOSE 95112-4919	Brutalist	N/A	N/A	N/A	Displays the original curtain wall, mirrored windows, metal sashes, and scalloped fascia. The building has been previously evaluated as ineligible for listing in the National Register and California Register. It was also evaluated as a Candidate City Landmark and determined to meet Criterion 6 as it embodies many characteristics of Modern architectural design, and therefore qualified as a Structure of Merit.	Yes		






Map Ref #	APN	Built Date (circa)	Address	Architectural Style	Primary Number	OHP Status Code	City HRI Designation Classification	Survey Notes	Evaluation Recommendation	Photograph 1	Photograph 2
38	23508002	1924	16 E YOUNGER AVE SAN JOSE 95112-4916	Minimal Traditional	N/A	N/A	N/A	Displays replacement windows, doors, and wall cladding.	Yes		
40	23508004	1924	48 E YOUNGER AVE SAN JOSE 95112-4916	Craftsman	N/A	N/A	N/A	Displays replacement windows, door, and wall cladding.	Yes		
42	23508064	1940	985 N 2ND ST SAN JOSE 95112-4929	Spanish Colonial Revival	N/A	N/A	N/A	Displays replacement windows.	Yes		
45	23508080	1951	954 N 1ST ST SAN JOSE 95112-4949	Contemporary	N/A	N/A	N/A	Displays replacement windows with original wall cladding and doors. This building has been previously evaluated as ineligible for listing in the National Register, California Register, and San Jose Historic Resources Inventory due to lack of historic significance.	No		





Map Ref #	APN	Built Date (circa)	Address	Architectural Style	Primary Number	OHP Status Code	City HRI Designation Classification	Survey Notes	Evaluation Recommendation	Photograph 1	Photograph 2
46	23508066	1928	943 N 2ND ST SAN JOSE 95112-4929	Tudor Revival	N/A	N/A	N/A	Displays original windows and doors.	Yes		
47	23508067	1925	941 N 2ND ST SAN JOSE 95112-4929	Minimal Traditional	N/A	N/A	N/A	Displays replacement windows and wall cladding.	Yes		
48	23508079	1951	940 N 1ST ST SAN JOSE 95112-4921	Minimal Traditional	N/A	N/A	N/A	Displays replacement windows and original doors. This building has been previously evaluated as ineligible for listing in the National Register, California Register, and San Jose Historic Resources Inventory due to lack of historic significance.	No		
49	23508068	1932	935 N 2ND ST SAN JOSE 95112-4929	Spanish Colonial Revival	N/A	N/A	N/A	Displays some original and replacement windows.	Yes		





Map Ref #	APN	Built Date (circa)	Address	Architectural Style	Primary Number	OHP Status Code	City HRI Designation Classification	Survey Notes	Evaluation Recommendation	Photograph 1	Photograph 2
51	23508069	1937	927 N 2ND ST SAN JOSE 95112-4929	Minimal Traditional	N/A	N/A	N/A	Displays replacement windows, original wall cladding, and a two-story addition.	Yes		
55	23508071	1929	915 N 2ND ST SAN JOSE 95112-4929	Craftsman	N/A	N/A	N/A	Displays original windows and replacement vinyl door.	Yes		
58	23508073	1947	25 E HEDDING ST SAN JOSE 95112-4910	None	N/A	N/A	N/A	Displays some original metal sash windows. Facade appears to be an addition off the original building.	No		
59	23508072	1947	37 E HEDDING ST SAN JOSE 95112-4910	Minimal Traditional	N/A	N/A	N/A	Displays original windows, doors, and wall cladding with added courtyard walls and slatted wooden privacy screens over windows on in the east facade.	Yes		





Map Ref #	APN	Built Date (circa)	Address	Architectural Style	Primary Number	OHP Status Code	City HRI Designation Classification	Survey Notes	Evaluation Recommendation	Photograph 1	Photograph 2
60	24902073	1960	890 N 1ST ST SAN JOSE 95112-6312	New Formalism	N/A	N/A	N/A	Constructed circa 1960 based on metal sash fixed windows and original metal entry door. Displays vinyl louvers and some replacement vinyl windows. This building has been previously evaluated as ineligible for listing in the National Register, California Register, and San Jose Historic Resources Inventory due to lack of historic significance.	No		
65	24902009	1946	870 N 1ST ST SAN JOSE 95112-6312	Contemporary	N/A	N/A	N/A	Displays partial window, door, and wall cladding replacements. Storefront added to west elevation of original residence in circa 1960. This building has been previously evaluated as ineligible for listing in the National Register, California Register, and San Jose Historic Resources Inventory due to lack of historic significance.	No		
67	24902008	1946	864 N 1ST ST SAN JOSE 95112-6312	Ranch	N/A	N/A	N/A	Displays replacement vinyl windows and original wood doors. This building has been previously evaluated as ineligible for listing in the National Register, California Register, and San Jose Historic Resources Inventory due to lack of historic significance.	No		
69	24902069	1978	852 N 1ST ST SAN JOSE 95112-6370	Corporate Modern	N/A	N/A	N/A	Displays original brick veneer, windows, and doors.	Yes		





Map Ref #	APN	Built Date (circa)	Address	Architectural Style	Primary Number	OHP Status Code	City HRI Designation Classification	Survey Notes	Evaluation Recommendation	Photograph 1	Photograph 2
72	24902072	1927	848 N 1ST ST SAN JOSE 95112-6312	Storybook	N/A	N/A	N/A	<p>Displays unevenly laid brick with a "California" stamp mark. Original exterior was likely plaster and the brick added at an unknown date. Mature foliage obscures the view of the building. The building was originally a single-family residence and converted to restaurant use in 1978.</p> <p>This building has been previously evaluated as ineligible for listing in the National Register, California Register, and San Jose Historic Resources Inventory due to lack of historic significance.</p>	No		
73	24902020	1925	848 N 2ND ST SAN JOSE 95112-6318	Folk with Dutch Colonial Revival detailing	N/A	N/A	N/A	<p>Displays some original windows and facade door, and replacement vinyl windows.</p>	Yes		
77	24902074	1939	832 N 1ST ST SAN JOSE 95112-6327	Minimal Traditional	N/A	N/A	N/A	<p>Displays original doors, windows, and cladding.</p> <p>This building has been previously evaluated as ineligible for listing in the National Register, California Register, and San Jose Historic Resources Inventory due to lack of historic significance.</p>	No		
78	24902023	1925	831 N 2ND ST SAN JOSE 95112-6318	Spanish Colonial Revival	N/A	N/A	N/A	<p>Displays original windows, doors, and wall cladding.</p>	Yes		





Map Ref #	APN	Built Date (circa)	Address	Architectural Style	Primary Number	OHP Status Code	City HRI Designation Classification	Survey Notes	Evaluation Recommendation	Photograph 1	Photograph 2
79	24902024	1924	825 N 2ND ST SAN JOSE 95112-6318	Tudor Revival	N/A	N/A	N/A	Displays original windows.	Yes		
80	24902064	1961	816 N 1ST ST SAN JOSE 95112-6301	Contemporary	N/A	N/A	N/A	Displays cinderblock walls and original stucco, and original windows and doors. This building has been previously evaluated as ineligible for listing in the National Register, California Register, and San Jose Historic Resources Inventory due to lack of historic significance.	No		
82	25904023	1956-1958	801 N 1ST ST SAN JOSE 95110	International	P43-000720 P43-000986	N/A	N/A	City Hall (P43-000720) - Displays original mirrored and frosted windows and doors. Architect - Donald F. Haines. Builder - Carl N. Swenson. The 1976-built 6-story annex was being demolished during time of the survey. In 2012, the building was evaluated and recommended eligible for listing in the National Register and California Register under Criteria A/1, B/2, and C/3. It was also found eligible for listing as a Santa Clara County Landmark under the County's Historic Preservation Ordinance. Lastly, the building was rated using the City of San Jose Historic Evaluation Rating system and found to likely qualify as a City Historic Landmark. Health Building (P43-000986) - Displays original windows and doors. Architect - Hollis Logue. Builders- Harrod & Williams and Don Gordon Co. The building was evaluated as ineligible for listing in the National Register, California Register, Santa Clara County Landmark, or San Jose City Landmark due to lack of integrity.	No		
83	24902025	1935	817 N 2ND ST SAN JOSE 95112-6318	Prairie	N/A	N/A	N/A	Displays replacement windows and doors, and original cladding.	Yes		





Map Ref #	APN	Built Date (circa)	Address	Architectural Style	Primary Number	OHP Status Code	City HRI Designation Classification	Survey Notes	Evaluation Recommendation	Photograph 1	Photograph 2
84	24902026	1926	813 N 2ND ST SAN JOSE 95112-6318	Spanish Colonial Revival	N/A	N/A	N/A	Displays original windows and replacement façade door.	Yes		
85	24902027	1926	807 N 2ND ST SAN JOSE 95112-6318	Prairie	N/A	N/A	N/A	Displays replacement doors and wall cladding with original windows.	Yes		
86	24902068	1975	800 N 1ST ST SAN JOSE 95112-6312	Brutalist	N/A	N/A	N/A	Displays original doors, windows, and wall cladding.	Yes		
87	24901066	1963	798 N 1ST ST SAN JOSE 95112-6302	Contemporary	N/A	N/A	N/A	Displays original windows, doors, and wall cladding. This building has been previously evaluated as ineligible for listing in the National Register, California Register, and San Jose Historic Resources Inventory due to lack of historic significance.	Yes		





Map Ref #	APN	Built Date (circa)	Address	Architectural Style	Primary Number	OHP Status Code	City HRI Designation Classification	Survey Notes	Evaluation Recommendation	Photograph 1	Photograph 2
88	24901028	1920	782 N 1ST ST SAN JOSE 95112-6326	Spanish Colonial Revival and Beaux Arts	N/A	N/A	N/A	The Fortune Building displays some replacement vinyl windows and original windows, and replacement doors dating to circa 1965.	Yes		
89	25905073	1963	777 N 1ST ST SAN JOSE 95112-6311	Corporate Modern	N/A	N/A	N/A	Displays original tile, asphalt, concrete, metal windows and doors, and exterior staircase. This building, known as the Swenson Building, was designed by John S. Bolles and constructed by general contractor Carl N. Swenson Co. The building was previously evaluated as ineligible for listing in the National Register and California Register, but was evaluated as eligible as a City Landmark under Criterion 6 as a well-executed example of a Mid-Century Modern-style office building, and under Criterion 7 as the work of a notable local architect.	No		
94	25905008	1910	61 ASBURY ST SAN JOSE 95110-2104	Craftsman	N/A	N/A	N/A	Displays original windows, doors, and cladding. This building was evaluated as ineligible for listing in the National Register, California Register, and as a San Jose City Landmark.	No		
111, 112	25917109 25917113	1973	681 N SAN PEDRO ST SAN JOSE 95110	New Formalism	N/A	N/A	N/A	Displays original doors, windows, and wall cladding.	Yes		

Map Ref #	APN	Built Date (circa)	Address	Architectural Style	Primary Number	OHP Status Code	City HRI Designation Classification	Survey Notes	Evaluation Recommendation	Photograph 1	Photograph 2
115	25905075	1961	732 N SAN PEDRO ST SAN JOSE 95110-2127	Minimal Traditional	N/A	N/A	N/A	Displays replacement windows and doors, and original wall cladding.	Yes		
116	25905076	1910	724 N SAN PEDRO ST SAN JOSE 95110-2127	Craftsman	P43-003439	N/A	N/A	Displays original windows and wall cladding, and replacement facade door. This building was previously evaluated as ineligible for listing in the National Register.	Yes		
117	25905050	1910	718 N SAN PEDRO ST SAN JOSE 95110-2127	Craftsman	P43-003437	N/A	N/A	Displays original windows, doors, and wall cladding. This building was previously evaluated as ineligible for listing in the National Register.	Yes		
118	25905077	1910	712 N SAN PEDRO ST SAN JOSE 95110-2127	Craftsman	P43-003436	N/A	N/A	Displays original wall cladding and a mix of replacement and original windows and doors. This building was previously evaluated as ineligible for listing in the National Register.	Yes		





Map Ref #	APN	Built Date (circa)	Address	Architectural Style	Primary Number	OHP Status Code	City HRI Designation Classification	Survey Notes	Evaluation Recommendation	Photograph 1	Photograph 2
120	25905053	1953	120 ASBURY ST SAN JOSE 95110-2105	Minimal Traditional	N/A	N/A	N/A	Displays original windows and board and batten siding.	Yes		
121	25905040	1914	747 MILLER ST SAN JOSE 95110-2121	Craftsman	N/A	N/A	N/A	Displays a mix of original and replacement windows, and replacement stucco and wood board wall cladding.	Yes		
123	25905041	1953	741 MILLER ST SAN JOSE 95110-2121	Minimal Traditional	N/A	N/A	N/A	A duplex with original metal casement windows, doors, stucco and board and batten siding.	Yes		
125		2005	750 MILLER ST SAN JOSE	NA	N/A	N/A	N/A	A building constructed circa 2005.	No		






Map Ref #	APN	Built Date (circa)	Address	Architectural Style	Primary Number	OHP Status Code	City HRI Designation Classification	Survey Notes	Evaluation Recommendation	Photograph 1	Photograph 2
129	25905065	1965	701 N 1ST ST SAN JOSE 95112-6303	New Formalism	N/A	N/A	N/A	Displays original windows and wall cladding; a mix of replacement and original doors, and new granite tile wall cladding.	Yes		
133	25905070	1940	711 N 1ST ST SAN JOSE 95112-6322	French Eclectic	P43-002365	N/A	N/A	Displays original windows, doors, and a wood shingle roof. Evaluated in 2000 as ineligible for listing in the National Register and California Register.	Yes		
134	25905058	1962	715 N 1ST ST SAN JOSE 95112-6309	Contemporary	N/A	N/A	N/A	Displays original windows and doors.	Yes		
137	24901027	0	778 N 1ST ST SAN JOSE 95112-6302	Contemporary	N/A	N/A	N/A	Displays a pier foundation, and original doors, windows, and wood and stucco cladding.	Yes		






Map Ref #	APN	Built Date (circa)	Address	Architectural Style	Primary Number	OHP Status Code	City HRI Designation Classification	Survey Notes	Evaluation Recommendation	Photograph 1	Photograph 2
138	24901026	1946	772 N 1ST ST SAN JOSE 95112-6302	Minimal Traditional	N/A	N/A	N/A	Displays new stucco wall cladding, windows and doors.	Yes		
139	24901025	1950	766 N 1ST ST SAN JOSE 95112-6330	Minimal Traditional	N/A	N/A	N/A	Displays replacement windows.	Yes		
140	24901024	1941	760 N 1ST ST SAN JOSE 95112-6302	Spanish Colonial Revival	N/A	N/A	N/A	Installation of new windows, doors, and wall cladding during time of survey.	Yes		
141	24901023	1941	754 N 1ST ST SAN JOSE 95112-6325	Spanish Colonial Revival	N/A	N/A	N/A	Displays original windows, doors, and exterior staircase.	Yes		





Map Ref #	APN	Built Date (circa)	Address	Architectural Style	Primary Number	OHP Status Code	City HRI Designation Classification	Survey Notes	Evaluation Recommendation	Photograph 1	Photograph 2
142	24901070	2000	738 N 1ST ST SAN JOSE 95112-6302	N/A	N/A	N/A	N/A	Built circa 2000.	No		
143	24901019	1934	730 N 1ST ST SAN JOSE 95112-6302	Spanish Colonial Revival	N/A	N/A	N/A	Displays curtain wall addition on façade and original windows.	Yes		
144	24901018	1920	724 N 1ST ST SAN JOSE 95112-6302	N/A	N/A	N/A	N/A	Displays curtain wall addition on façade, altered entry location, replacement stucco, and original wood windows.	No		
145	24901017	1948	716 N 1ST ST SAN JOSE 95112-6324	Minimal Traditional	N/A	N/A	N/A	Displays replacement vinyl windows.	Yes		






Map Ref #	APN	Built Date (circa)	Address	Architectural Style	Primary Number	OHP Status Code	City HRI Designation Classification	Survey Notes	Evaluation Recommendation	Photograph 1	Photograph 2
146	24901016	1922	708 N 1ST ST SAN JOSE 95112-6323	Beaux Arts	N/A	7R	CS	Displays original windows, doors and decorative detailing. Listed in the City's Historic Resources Inventory as a Contributing Structure.	Yes		
148	25918063	1970	110 W TAYLOR ST SAN JOSE 95110-2131	Corporate Modern	N/A	N/A	N/A	Displays original doors, windows, and wall cladding.	Yes		
149	25918004	1910	668 N SAN PEDRO ST SAN JOSE 95110- 2125	Greek Revival	N/A	N/A	N/A	Displays original doors, windows, wall cladding, and decorative elements.	Yes		
150	25918003	1910	666 N SAN PEDRO ST SAN JOSE 95110- 2125	Greek Revival	N/A	N/A	N/A	Residence dates to circa 1910 and displays original wall cladding, and replacement doors and windows.	Yes		





Map Ref #	APN	Built Date (circa)	Address	Architectural Style	Primary Number	OHP Status Code	City HRI Designation Classification	Survey Notes	Evaluation Recommendation	Photograph 1	Photograph 2
151	25918002	1910	664 N SAN PEDRO ST SAN JOSE 95110-2125	Greek Revival	N/A	N/A	N/A	Residence dates to circa 1910 and displays original wall cladding and mix of original and replacement windows.	Yes		
152	25918001	1915	145 GEORGE ST SAN JOSE 95110-2116	Folk Victorian and Colonial Revival	N/A	N/A	N/A	Displays original windows, doors, wall cladding and decorative elements. Built circa 1915.	Yes		
153	25918020	1910	141 GEORGE ST SAN JOSE 95110-2116	Greek Revival	N/A	N/A	N/A	Displays original wall cladding, windows, and a replacement door. The bay window appears to be a later addition.	Yes		
154	25918016	1890	665 MILLER ST SAN JOSE 95110-2119	Folk	N/A	N/A	IS	Displays original windows, doors and wall cladding, with addition off the west elevation. Building dates to circa 1890. This resource is listed in the City's Historic Resources Inventory as an Identified Structure.	Yes		




Map Ref #	APN	Built Date (circa)	Address	Architectural Style	Primary Number	OHP Status Code	City HRI Designation Classification	Survey Notes	Evaluation Recommendation	Photograph 1	Photograph 2
155	25918017	1900	663 MILLER ST SAN JOSE 95110-2119	Folk Victorian	N/A	N/A	IS	Displays original windows, door and wall cladding. Dates to circa 1900. This resource is listed in the City's Historic Resources Inventory as an Identified Structure.	Yes		
156	25918018	1900	659 MILLER ST SAN JOSE 95110-2119	Queen Anne	N/A	N/A	IS	Displays a replacement facade door and original wall cladding, windows, and decorative elements. Porch decorative detailing may not be original. An addition is located off the west elevation. Built circa 1900. This resource is listed in the City's Historic Resources Inventory as an Identified Structure.	Yes		
157	25918019	1900	651 MILLER ST SAN JOSE 95110-2119	Queen Anne	N/A	N/A	IS	This property includes two buildings: a circa 1900 Queen Anne-style residence and a circa 1965 Minimal Traditional-style duplex. Both have original wall cladding, replacement doors, and a mix of replacement and original windows. This resource is listed in the City's Historic Resources Inventory as an Identified Structure.	Yes	 	
159	25918039	1931	148 GEORGE ST SAN JOSE 95110-2115	Mission	N/A	N/A	N/A	Displays replacement windows and doors and partial wall cladding replacement on the north elevation.	Yes		





Map Ref #	APN	Built Date (circa)	Address	Architectural Style	Primary Number	OHP Status Code	City HRI Designation Classification	Survey Notes	Evaluation Recommendation	Photograph 1	Photograph 2
170	25918038	0	638 N SAN PEDRO ST SAN JOSE 95110-2262	N/A	N/A	N/A	N/A	Possibly a circa 1900 residence recently renovated. Displays new wall cladding, windows, and doors. No original decorative features remain.	No		
171	25918042	1931	126 GEORGE ST SAN JOSE 95110-2115	Minimal Traditional	N/A	N/A	N/A	Displays original windows and wall cladding.	Yes		
172	25918043	1900	112 GEORGE ST SAN JOSE 95110-2115	Italianate	N/A	N/A	IS	Displays a mix of replacement and original windows, original wide wood board siding, and a replacement railing. Dates to circa 1900. This resource is listed in the City's Historic Resources Inventory as an Identified Structure.	Yes		
173	25918044	1925	80 GEORGE ST SAN JOSE 95110-2112	None	N/A	N/A	N/A	The property contains two buildings: a circa 1900 and circa 1925 multi-family building. The circa 1900 residence was likely converted to apartments around 1950. It displays major alterations to the windows, wall cladding, and fenestration patterns, as well as the addition of large porches on the west side of the building. The building may have once represented the Queen Anne style, but many of the character-defining features of the style no longer remain. The circa 1925 styleless apartment building displays window and door alterations.	No		





Map Ref #	APN	Built Date (circa)	Address	Architectural Style	Primary Number	OHP Status Code	City HRI Designation Classification	Survey Notes	Evaluation Recommendation	Photograph 1	Photograph 2
174	25918045	1912	68 GEORGE ST SAN JOSE 95110-2112	Queen Anne	N/A	N/A	N/A	Displays original windows, storefront, replacement asbestos siding, and some original triple bevel wood siding. It is unclear if the building originally displayed this ground plan or if it displays an addition dating to the early 20th century.	Yes		
175	25918046	1927	64 GEORGE ST SAN JOSE 95110-2112	Prairie	N/A	N/A	N/A	Displays original windows and doors, and replacement stucco wall cladding. The façade entry is likely a reconfiguration for a duplex conversion completed at an unknown date.	Yes		
176	25918047	1920	54 GEORGE ST SAN JOSE 95110-2112	Craftsman	N/A	N/A	IS	Displays original windows, double beveled wall cladding, and door, as well as replacement stucco in gable and staircase railing. This resource is listed in the City's Historic Resources Inventory as an Identified Structure.	Yes		
177	25918048	1958	44 GEORGE ST SAN JOSE 95110-2114	Minimal Traditional	N/A	N/A	N/A	Displays replacement windows and original wood doors.	Yes		





Map Ref #	APN	Built Date (circa)	Address	Architectural Style	Primary Number	OHP Status Code	City HRI Designation Classification	Survey Notes	Evaluation Recommendation	Photograph 1	Photograph 2
178	25918049	1910	34 GEORGE ST SAN JOSE 95110-2112	Folk	N/A	N/A	IS	Under construction during the survey. Displays original wide wood board wall cladding and wood double hung windows. Some window glazing missing. Foundation work in progress. Dates to circa 1910. This resource is listed in the City's Historic Resources Inventory as an Identified Structure.	Yes		
183	25918061	1966	675 N 1ST ST SAN JOSE 95112-5118	Corporate Modern, New Formalism	N/A	N/A	N/A	Three buildings on the property.	Yes		
185	25918033	1941	35 GEORGE ST SAN JOSE 95110-2113	Contemporary	N/A	N/A	N/A	Displays original windows and possible cladding replacement.	Yes		
186	25918066	1901	667 N 1ST ST SAN JOSE 95112-5117	N/A	N/A	7R	N/A	Displays replacement windows, doors, wall cladding, window frames, and staircase.	No		





Map Ref #	APN	Built Date (circa)	Address	Architectural Style	Primary Number	OHP Status Code	City HRI Designation Classification	Survey Notes	Evaluation Recommendation	Photograph 1	Photograph 2
188	24942070	1915	698 N 1ST ST SAN JOSE 95112-5109	Folk Victorian	N/A	3D	N/A	Displays original windows, doors, and wall cladding.	Yes		
189	25918032	1920	651 N 1ST ST SAN JOSE 95112-5117	Craftsman and Colonial Revival	N/A	7R	CS	Displays original windows and doors. Replacement stucco dates to circa 1980s. This resource is listed in the City's Historic Resources Inventory as a Contributing Structure.	Yes		
190	24942071	1920	20 E TAYLOR ST SAN JOSE 95112-5007	Craftsman	N/A	7R	N/A	The building's interior, windows, and doors were destroyed by fire at an unknown date.	No		
191	24942069	1906	692 N 1ST ST SAN JOSE 95112-5109	Folk Victorian and Colonial Revival	N/A	7R	N/A	Displays original windows, doors, wall cladding, and decorative elements.	Yes		





Map Ref #	APN	Built Date (circa)	Address	Architectural Style	Primary Number	OHP Status Code	City HRI Designation Classification	Survey Notes	Evaluation Recommendation	Photograph 1	Photograph 2
192	24942068	1918	684 N 1ST ST SAN JOSE 95112-5109	Prairie	N/A	7R	N/A	Displays original doors and windows, and replacement stucco wall cladding.	Yes		
193	24942067	1920	678 N 1ST ST SAN JOSE 95112-5109	Dutch Colonial Revival	N/A	7R	N/A	Displays original doors and windows, and replacement stucco wall cladding.	Yes		
194	24942086	1922	672 N 1ST ST SAN JOSE 95112-5109	Spanish Colonial Revival	N/A	7R	N/A	Displays original doors, windows, and bell tower.	Yes		
195	24942065	1908	668 N 1ST ST SAN JOSE 95112-5109	Craftsman	N/A	3D	CS	Displays replacement stucco, original windows, and doors. Listed in the City's Historic Resources Inventory as a Contributing Structure.	Yes		





Map Ref #	APN	Built Date (circa)	Address	Architectural Style	Primary Number	OHP Status Code	City HRI Designation Classification	Survey Notes	Evaluation Recommendation	Photograph 1	Photograph 2
198	24942073	1964	644 N 1ST ST SAN JOSE 95112-5109	A-frame	N/A	7R	N/A	Displays original windows, doors, and wall cladding, and replacement gable metal cladding.	Yes		
199	24942079	1969	636 N 1ST ST SAN JOSE 95112-5109	Contemporary	N/A	7R	N/A	Displays prominent roofline, original windows, and doors. Possible addition at rear.	Yes		
200	24942057	1905	638 N 1ST ST SAN JOSE 95112-5149	Prairie	N/A	7R	CS	Displays original windows, doors, and wall cladding, and altered entryway. Also has address: 630 N 1st Street. Listed in the City's Historic Resources Inventory as a Contributing Structure.	Yes		
201, 202	24942075 24942074	1968	606 N 1ST ST SAN JOSE 95112-5109	Contemporary	N/A	7R	N/A	Display original wall cladding, roofline, windows, doors, and prominent roofline.	Yes		





Map Ref #	APN	Built Date (circa)	Address	Architectural Style	Primary Number	OHP Status Code	City HRI Designation Classification	Survey Notes	Evaluation Recommendation	Photograph 1	Photograph 2
203	25918052	1900	629 N 1ST ST SAN JOSE 95112-5135	Queen Anne	N/A	7R	CS	Displays original windows, wall cladding, leaded glass, bay window, decorative dentil molding, and cornice moldings. Highly decorative cornice brackets. Built circa 1900. This resource is listed in the City's Historic Resources Inventory as a Contributing Structure.	Yes		
204	25918053	1939	625 N 1ST ST SAN JOSE 95112-5134	Art Deco	N/A	7R	N/A	Displays original windows, molding, and wall cladding.	Yes		
205	25918054	1914	623 N 1ST ST SAN JOSE 95112-5110	Craftsman	N/A	7R	CS	Displays original windows, doors, and wall cladding. This resource is listed in the City's Historic Resources Inventory as a Contributing Structure.	Yes		
206	25918055	1907	619 N 1ST ST SAN JOSE 95112-5110	Craftsman	N/A	7R	CS	Displays original windows, doors, and wall cladding. This resource is listed in the City's Historic Resources Inventory as a Contributing Structure.	Yes		





Map Ref #	APN	Built Date (circa)	Address	Architectural Style	Primary Number	OHP Status Code	City HRI Designation Classification	Survey Notes	Evaluation Recommendation	Photograph 1	Photograph 2
207	25918064	1925	607 N 1ST ST SAN JOSE 95112-5110	Colonial Revival	N/A	3D	CS	Karl H. Plate House (aka Carter Waxman Building) Displays original door and windows with replacement stucco wall cladding. This resource is listed in the City's Historic Resources Inventory as a Contributing Structure.	Yes		
208	25918058	1906	35 HOBSON ST SAN JOSE 95110-2252	Colonial Revival	N/A	N/A	N/A	Displays a mix of original and replacement windows, and replacement stucco.	Yes		
209	25918057	1907	601 N 1ST ST SAN JOSE 95112-5110	Mission	N/A	7R	CS	Displays replacement windows, doors, and stucco. This resource is listed in the City's Historic Resources Inventory as a Contributing Structure.	Yes		
210	25919103	1975	595 N 1ST ST SAN JOSE 95112-5314	Contemporary	N/A	7R	N/A	Appears recently renovated.	Yes		





Map Ref #	APN	Built Date (circa)	Address	Architectural Style	Primary Number	OHP Status Code	City HRI Designation Classification	Survey Notes	Evaluation Recommendation	Photograph 1	Photograph 2
211	24943051	1947	588 N 1ST ST SAN JOSE 95112-5319	Minimal Traditional	N/A	7R	N/A	Displays original windows and replacement entry doors.	Yes		
212	24943050	1947	588 N 1ST ST SAN JOSE 95112-5327	Mansard	N/A	7R	N/A	Displays replacement windows and doors. Composite shingle on the mansard roof.	Yes		
213	24943049	1936	576 N 1ST ST SAN JOSE 95112-5349	Streamline Moderne	N/A	7R	N/A	Name: "The Maxwell." Displays replacement windows.	Yes		
214	24943048	1936	568 N 1ST ST SAN JOSE 95112-5348	Streamline Moderne	N/A	7R	CS	Name: "The Maxwell." Displays replacement windows. Listed in the City's Historic Resources Inventory as a Contributing Structure.	Yes		






Map Ref #	APN	Built Date (circa)	Address	Architectural Style	Primary Number	OHP Status Code	City HRI Designation Classification	Survey Notes	Evaluation Recommendation	Photograph 1	Photograph 2
215	24943047	1901	560 N 1ST ST SAN JOSE 95112-5319	Unknown	N/A	7R	CS	Building obscured by vegetation. Cannot provide description. Listed in the City's Historic Resources Inventory as a Contributing Structure.	Yes		
216	24943083	1961	556 N 1ST ST SAN JOSE 95112-5300	Contemporary	N/A	7R	N/A	Displays original concrete curtain wall, concrete pier foundation, windows, and doors.	Yes		
217	24943045	1959	540 N 1ST ST SAN JOSE 95112-5319	International	N/A	7R	N/A	Displays original aluminum windows and doors, and stone wall cladding.	Yes		
218	24943042	1948	523 N 2ND ST SAN JOSE 95112-5316	Ranch	N/A	N/A	N/A	Displays replacement vinyl windows.	Yes		





Map Ref #	APN	Built Date (circa)	Address	Architectural Style	Primary Number	OHP Status Code	City HRI Designation Classification	Survey Notes	Evaluation Recommendation	Photograph 1	Photograph 2
219	24943044	1965	510 N 1ST ST SAN JOSE 95112-5321	International	N/A	N/A	N/A	Name: "Empire Building." Displays original windows, doors, and metal shade structures. Built circa 1965.	Yes		
220	25919098	1968	555 N 1ST ST SAN JOSE 95112-5326	Corporate Modern	N/A	7R	N/A	Displays original wall cladding, brick veneer, windows, and possibly replacement door.	Yes		
222	25919104	1962	515 N 1ST ST SAN JOSE 95112-5320	International	N/A	7R	N/A	Displays original stone cladding, windows, and doors.	Yes		
223	25919061	1936	16 AYER AVE SAN JOSE 95110-2201	Spanish Colonial Revival	N/A	7R	CS	Displays replacement and original windows. This resource is listed in the City's Historic Resources Inventory as a Contributing Structure.	Yes		





Map Ref #	APN	Built Date (circa)	Address	Architectural Style	Primary Number	OHP Status Code	City HRI Designation Classification	Survey Notes	Evaluation Recommendation	Photograph 1	Photograph 2
224	25919062	1932	15 HAWTHORNE WAY SAN JOSE 95110-2247	Spanish Colonial Revival	N/A	5S2	CS	Displays original windows, doors, and balconies. This resource is listed in the City's Historic Resources Inventory as a Contributing Structure.	Yes		
225	25919086	1917	485 N 1ST ST SAN JOSE 95112-4041	Spanish Colonial Revival	N/A	N/A	CS	The McMahon Building displays original door and replacement windows. This resource is listed in the City's Historic Resources Inventory as a Contributing Structure.	Yes		
226	25919087	1955	481 N 1ST ST SAN JOSE 95112-4031	International	N/A	N/A	N/A	Displays original windows, doors, and rock veneer.	Yes		
227	25920013	1925	475 N 1ST ST SAN JOSE 95112-4018	Spanish Colonial Revival	N/A	7N	CS	Displays original windows, doors and wall cladding. This resource is listed in the City's Historic Resources Inventory as a Contributing Structure.	Yes		


Map Ref #	APN	Built Date (circa)	Address	Architectural Style	Primary Number	OHP Status Code	City HRI Designation Classification	Survey Notes	Evaluation Recommendation	Photograph 1	Photograph 2
231	25920015	1955	447 N 1ST ST SAN JOSE 95112-4018	Minimal Traditional	N/A	N/A	N/A	Displays replacement windows and doors, and replacement wall cladding on second story.	Yes		
232	24944044	1920	20 HENSLEY ST SAN JOSE 95112-4026	Mission	N/A	N/A	N/A	Displays replacement windows.	Yes		
233	24944067	1890	447 N 2ND ST SAN JOSE 95112-4012	Queen Anne	N/A	N/A	CS	Displays original windows and doors. Built circa 1890. Listed in the City's Historic Resources Inventory as a Contributing Structure.	Yes		
234	24944045	1890	444 N 1ST ST SAN JOSE 95112-4001	Shingle and Richardsonian Romanesque	N/A	N/A	CS	Displays original windows and doors. Large facade addition with stucco cladding. Original cladding was wood shingle. Built circa 1890. Listed in the City's Historic Resources Inventory as a Contributing Structure.	Yes		





Map Ref #	APN	Built Date (circa)	Address	Architectural Style	Primary Number	OHP Status Code	City HRI Designation Classification	Survey Notes	Evaluation Recommendation	Photograph 1	Photograph 2
235	24944066	1890	443 N 2ND ST SAN JOSE 95112-4012	Folk	N/A	N/A	IS	Displays original and replacement windows. Built circa 1890. Listed in the City's Historic Resources Inventory as an Identified Structure.	Yes		
236	24944068	1915	440 N 1ST ST SAN JOSE 95112-4024	Craftsman and Mission	N/A	N/A	N/A	Displays original windows and doors with large addition of rear.	Yes		
237		1990		N/A	N/A	N/A	N/A	Circa 1990 apartment complex.	No		
239	25920043	1924	445 N 1ST ST SAN JOSE 95112-4030	Mission and Beaux Arts	N/A	N/A	CS	Displays replacement vinyl windows, original doors, and mostly original wall cladding with recent brick cladding added to east elevation. This resource is listed in the City's Historic Resources Inventory as a Contributing Structure.	Yes		


Map Ref #	APN	Built Date (circa)	Address	Architectural Style	Primary Number	OHP Status Code	City HRI Designation Classification	Survey Notes	Evaluation Recommendation	Photograph 1	Photograph 2
241	25920045	1940	Ryland Park	None	N/A	N/A	CCL	<p>Ryland Park includes a playground, pool, pool house, hardscaped areas, and landscaped areas. The park dates to circa 1940. Many features of the park appear to have been renovated in the 2000s.</p> <p>The Ryland Pool was evaluated in 2007 as not eligible for listing in the National Register or California Register, but was identified as a City Landmark candidate and listed in the City's Historic Resources Inventory as such.</p>	No		
244		1909		N/A	N/A	N/A	N/A	The 1909 building is no longer extant and replaced by a circa 2000 apartment building.	No		
246		1909	396 N 1ST ST SAN JOSE 95112-4050	Spanish Colonial Revival with Beaux Arts detailing	P43-002354	5S2	CLS	The Borchers Bros. 1909 building façade remains extant along North First Street; however, the remainder of the building is a circa 1990 apartment building. Listed in the City's Historic Resources Inventory as a City Landmark.	Yes		
249	24944088	1964	380 N 1ST ST SAN JOSE 95112-4050	New Formalism	N/A	N/A	N/A	Displays original windows, doors, and detailing.	Yes		

Map Ref #	APN	Built Date (circa)	Address	Architectural Style	Primary Number	OHP Status Code	City HRI Designation Classification	Survey Notes	Evaluation Recommendation	Photograph 1	Photograph 2
251		2007		N/A	N/A	N/A	N/A	The 1909 building was replaced with circa 2007 multi-family housing development.	No		
253	24944087	1984	360 N 1ST ST SAN JOSE 95113	N/A	N/A	N/A	N/A	Built between 1980 and 1987.	No		
254		2007	1 E JULIAN ST SAN JOSE	N/A	N/A	N/A	N/A	The 1909 building was replaced by a circa 2007 building.	No		
255	24944060	1915	315 N 2ND ST SAN JOSE 95112-4028	Prairie	N/A	N/A	N/A	Displays the original door and replacement vinyl windows and stucco wall cladding. Built circa 1915.	Yes		

Map Ref #	APN	Built Date (circa)	Address	Architectural Style	Primary Number	OHP Status Code	City HRI Designation Classification	Survey Notes	Evaluation Recommendation	Photograph 1	Photograph 2
256	24944059	1900	311 N 2ND ST SAN JOSE 95112-4003	Classical Revival	N/A	1D, 5S2	NRD: CLS	The Moody Flats Apartments is within a National Register-listed historic district and is a City Landmark.	Yes		
257	24944057	1905	31 E JULIAN ST SAN JOSE 95112-4006	Colonial Revival	N/A	1D, 2S	NRD: CLD	The Nathan Flats & House is within a National Register-listed historic district and within a City Landmark District.	Yes		
258	24944090	1905	45 E JULIAN ST SAN JOSE 95112-4006	Colonial Revival	N/A	1D	NRD: CLD	Nathan House. Listed in the City's Historic Resources Inventory as being within both a National Register-listed historic district and a City Landmark District.	Yes		
259		2005	350 N 2ND ST SAN JOSE	N/A	N/A	N/A	N/A	The 1909 building was replaced by a building constructed in 2005.	No		

Map Ref #	APN	Built Date (circa)	Address	Architectural Style	Primary Number	OHP Status Code	City HRI Designation Classification	Survey Notes	Evaluation Recommendation	Photograph 1	Photograph 2
264	24944031	1901	336 N 2ND ST SAN JOSE 95112-4015	Queen Anne/Eastlake	N/A	1D	NRD; CLD; CS	Displays original doors and wall cladding, and replacement windows. Built circa 1888. The building is within a National Register-listed historic district and a City Landmark District, as well as listed in the City's Historic Resources Inventory as a Contributing Structure.	Yes		
265	24944030	1901	334 N 2ND ST SAN JOSE 95112-4015	Colonial Revival	N/A	1D	NRD; CLD; CS	Displays original windows, doors and wall cladding. Built circa 1888. The building is within a National Register-listed historic district and a City Landmark District, as well as listed in the City's Historic Resources Inventory as a Contributing Structure.	Yes		
266	24944029	1905	332 N 2ND ST SAN JOSE 95112-4015	Colonial Revival	N/A	1D	NRD; CLD; CS	Displays original windows and wall cladding, and replacement doors. The building is within a National Register-listed historic district and a City Landmark District, as well as listed in the City's Historic Resources Inventory as a Contributing Structure.	Yes		
268	24944023	1890	73 E JULIAN ST SAN JOSE 95112-4046	Italianate	N/A	1D	NRD; CLD	The building is within both a National Register-listed historic district and a City Landmark District.	Yes		

Map Ref #	APN	Built Date (circa)	Address	Architectural Style	Primary Number	OHP Status Code	City HRI Designation Classification	Survey Notes	Evaluation Recommendation	Photograph 1	Photograph 2
269	24943088	1959	490 N 1ST ST SAN JOSE 95112-4043	Contemporary	N/A	7R	N/A	Displays original metal windows and doors.	Yes		
270	24943064	1907	460 N 1ST ST SAN JOSE 95112-4044	Spanish Colonial Revival	N/A	N/A	CS	Mission Court Apartments. Displays original windows and doors. Listed in the City's Historic Resources Inventory as a Contributing Structure.	Yes		
276	25918041	1931	142 GEORGE ST SAN JOSE 95110-2115	Spanish Colonial Revival	N/A	N/A	N/A	Displays replacement and original windows.	Yes		
277	24943087	1957	480 N 1ST ST SAN JOSE 95112-4040	International	N/A	N/A	N/A	Connected to 490 North First Street. Displays original windows and doors. May have replacement wall cladding.	Yes		

Map Ref #	APN	Built Date (circa)	Address	Architectural Style	Primary Number	OHP Status Code	City HRI Designation Classification	Survey Notes	Evaluation Recommendation	Photograph 1	Photograph 2
179, 180	25918051	1965	633 N 1ST ST SAN JOSE 95112-5110	Ranch	N/A	N/A	N/A	Dates to circa 1965. Original windows, doors and wall cladding.	Yes		
54, 56, 57	23508076 23505075 23508074	1977	914 N 1ST ST SAN JOSE 95112-4919	Corporate Modern	N/A	N/A	N/A	Displays original doors, windows, and cladding.	Yes	