

SITE VISIT/FIELD NOTES

Date: 9/9/20 Time: 11:11 am

Surveyor: Crake, AEM

Project Name: 1750 Moorpark, San Jose, CA
Address: "

Existing Conditions:

Church Building

Surrounding Area (structures, trees, shrubs, ground surface):

dry vegetation pile

freeway & on-ramp

Conditions of Note (restricted areas, stained soil, monitoring wells):

none

Resources (on or near, water bodies, ditches, vegetation):

large trees