

	Project Name	Discharge Type	Recv. Waterbody(ies)	Date of Discharge	Time of Discharge Discovery	Regulatory Agency Notification Time	Inspector Arrival Time	Responding Crew Arrival Time	Discharge Duration (Mltry Time)	Est. Volume (gal)	Est. Flow Rate (gal/day)	Chlorine Residual (mg/L)	pH	Discharge Turbidity (NTU)	Implemented BMPs & Corrective Actions	
1	3601 Carick Place Way	water main break/flush	Coyote creek	2/19/2010	6:15am		6:40am	9:00	1:10	25	1750	0.87	4	54	gravel bags/dechlor	This is a discharge from a trench which was being pumped out to access the
2	Neiman Blvd	Service line break	Thompson creek	12/5/2009	11:00pm est.		12:00am est.	1:00am	3:00						gravel bags	No data collected on this discharge
3	N. First St/Tasman	water main break/flush	Guadalupe river	1/11/2010	1:00pm est.		1:30pm est.	2:00pm est.	5:00						gravel bags	No data collected on this discharge
4	Liberty/Moffat	water main break/flush	Guadalupe river	5/5/2010	10:00am est.		10:30am est.	11:30am est.	5:00						gravel bags	No data collected on this discharge